



SERVICE INFORMATION

Gust.Serv.- Techn.Office
VKT gi/wi-ba

Motorcycles 1 and 2 cyl.
Group: Transmission

München, 4th. Nov. 66
Nr. 2/66 (237) en.

Re: Kickstarter pressure spring

Dear Sirs,

To prevent a disagreeable noise developing occasionally from the kickstarter ratchet mechanism occurring especially when the transmission oil is still ropy, the coil pitch of the pressure spring, part number 10 56 116, has now been changed to left.

This modification has become standard feature on the model

R 27	commencing with frame Nr.	386 865
R 50	" " " Nr.	643 190
R 60	" " " Nr.	1 810 530
R 69 S	" " " Nr.	662 145

The part number remains unchanged for all models.

Very truly yours,

BAYERISCHE MOTOREN WERKE
Aktiengesellschaft

ppa.

i.V.

Winkler

Delleske