



SERVICE INFORMATION

Techn. Customer Service
VKT 20 Er/wi-wi

Motorcycles R50, 60, 69S
Groupe: Engine

München 0/10/67
No. 7/67 (257) eng

Supplement 1

Re.: Air filter and carburetors

Applicable to
U S Models with
TELESCOPIC FORK

Dear Sirs,

In order to safeguard the correct fuel level, it is important to check - after having repaired the needle valve of the new carburetor execution - the distance of 22 mm between the flange surface of the cover and the bottom side of the transmission lever, or to adjust, resp. the distance by rebending slightly the transmission lever to the indicated value. See sketch overleaf!

At the same time we repeat the list of the uniform intake air filter assembly, as well as that one of the new carburetors provided with lever floats and the new order numbers, which have generally been introduced from the beginning of 1 st September 1967.

	<u>R 50</u>	<u>R 60</u>	<u>R 69 S</u>
Air filter compl.	13 72 1250314	13 72 1250314	13 72 1250314
Micro-Star filter element	13 72 1250315	13 72 1250315	13 72 1250315
Carburetor, right	13 11 0039073	13 11 0039076	13 11 0039056
Carburetor, left	13 11 0039074	13 11 0039077	13 11 0039057
Main jet	13 11 0039241	13 11 0039292	13 11 0039248

Yours very truly

BAYERISCHE MOTOREN WERKE
Aktiengesellschaft

ppa.

i.V.

(Makowitzki)

(Delleske)

Sketch on overleaf

Kenntnis genommen — Pris connaissance — Noted — Tomado nota — Preso conoscenza
Betriebsleitung | Werkstatt | KD-Ansprache | Geschäftsbereich | ... | Ablage — Archives — File — Archivio

SERVICE-INFORMATION Motorräder
Nr. 7/67 - Nachtrag I v. 20.9.67

