



SERVICE INFORMATION

Cust.Serv.-Techn.Office
VKT Er/wi/ba

Motorcycles R 27
Group: Rear wheel drive

München, 28 June 1966
Nr. 1/66 (232) er

Re: Hardy disc between shock absorber flange on drive shaft
and coupling flange on transmission output shaft

Dear Sirs,

The export machines of the R 27 model bound for countries with tropical climate now feature as standard equipment a hardy disc made of rubber, part number 30 38 180 (special execution), instead of the normally installed Vulkollan disc.

The Vulkollan hardy disc (part Nr. 30 38 476) remains unchanged on all other standard production machines.

Very truly yours,

BAYERISCHE MOTOREN WERKE
Aktiengesellschaft

zpa.

i.V.

Makowitzki
Makowitzki

Delleske
Delleske