

SERVICE MEDICAL CARROLL SERVICE AND CARROLL SE

Cust.Serv.- Dept.Techn. VKT Gi/wi-ba

Motorcycles R50 & R60 Group: Engine

München, March 13,67 No. 2/67 (246) en.

Re: New breather

Dear Sirs,

With the scope of standardizing the components the breather of the R 69S i.e. the sport model is installed on the R 50 models effective of frame No. 644 286 and on the R 60 models effective of No. 1812 443.

Owing to this measure the following parts are superseded:

1	Breather plate with pressed-in			
	drive pins	00	31	170
	Pressure spring for the breather	0.0	~-	
	plate	00	3 T	152
1	Spring ring	99	33	451

New parts:

1 Breather	plate with cast-on drive			
pins	[[요즘 : 하다 하다 하다 하다 하다] -	00	31	171
l Lock ring	for breather plate	00	31	707
l Washer	요즘 보는 그런 그렇는 그를 보는 것 같다.	10	30	116

When exchanging the gear train for crankshaft and camshaft or the breather elements it is absolutely necessary to bear in mind that the new breather pertains to the gear train, part No. 00 16 379 - 399, and the hitherto installed breather to the gear train, Part No. 00 16 329 - 349.

A confusion of the parts is possible and would entail an insufficient ventilation of the crankcase.

Very truly yours,

BAYERISCHE MOTOREN WERKE Aktiengesellschaft

ppa.

i.V.

Makowitzki

Delleske