



SERVICE INFORMATION

Customer Service
V.GmbH/B&S, N.J.

Motorcycles R50, R60, R69S
R50US, R60US, R69US
Engine

New Jersey, Dec. 1969
No. 2/69 (277)

RE: Crankshaft

Gentlemen:

Effective with

R50/R50US	Engine No. 647306
R60/R60US	Engine No. 1816946
R69S/R69US	Engine No. 665230

crankshafts with part number

R50/R50US	11 21 0 016 060
R60/R60US	11 21 0 016 062
R69S/R69US	11 21 0 016 066

respectively, are installed.

These crankshafts can be installed on all twins manufactured after 1961.

Caution: Whenever one of the above mentioned crankshafts is installed a spacer

Part No. 26 11 3 038 126

must be installed between the generator bearing and the crankshaft timing gear.

Bayerische Motoren Werke
Aktiengesellschaft

i. a. Volker

- Volker Beer -

Kenntnis genommen — Pris connaissance — Noted — Tomado nota — Preso conoscenza

Ablage — Archives — File — Archivo

Betriebsleitung

Werkstatt

KD-Annahme

Gewährl.-Sachb.

E-Teildienst

Betriebsleitung

Werkstatt