

SERVICE INFORMATION

Cust.Serv.- Techn. Office
VKT gi/wi-ba

BMW R27 Motorcycles
Group: Engine

München, Oct. 11, 66
Suppl. Nr. 4/66 (231) en.

SUPPLEMENT #1

Re: Pistons R 27

Dear Sirs,

Supplementing our Service Information Nr. 4/66 (231) we wish to inform you that a deplorable mistake has crept in when stating the part numbers for the new pistons with increased fire ridge.

The correct part numbers must read:

	Part Nr.	Size
Piston normal	0012 123	67.95
	0012 124	67.96
	0012 125	67.97
Piston, first oversize	0012 126	68.45
	0012 127	68.46
	0012 128	68.47
Piston, second oversize	0012 129	68.95
	0012 131	68.96
	0012 132	68.97

The pistons for the first and second oversizes will be available early in December approximately.


Very truly yours,

BAYERISCHE MOTOREN WERKE
Aktiengesellschaft

ppa.

i.A.


Makowitzki


Hertrampf